

Interim Progress Report Contract RD-84 WO. 28-2000-2

Job No. 175

This report covers the work done through January 1956 in modifying 4 type K-20 cameras as per above referenced Work Order.

- 1. Battery cases have been designed, built, and corrosion proofed. These cases mount inside the optical compartment with a vent to the outside only.
- 2. The shutter timing problem has been solved by use of a capacitance-delayed relay. A similar system is expected to be used for the lamp flash timing and is now undergoing investigation.
- 3. The general problem of improving the uniformity of illumination is now being investigated.
- 4. Labyrinth seals have been built between the cover and the camera body.
- 5. All cameras have been checked and reconditioned by Fairchild Camera and Instrument Co.

PHOTOMECHANISMS, INC. Huntington Station, N.Y.

February 6, 1956

SECRET